

LES CODES D'OPTIONS DES TELEVISEURS FLX.XX :

| Référence | Châssis | RC | Tuner | OPTION | | | | |
|-------------|------------|------|----------------|--------|-----|-----|-----|-----|
| | | | | 1 | 2 | 2 | 4 | 5 |
| 25PT800A/19 | FL1. 1 7AA | 7136 | FQ916MF/LIF | 020 | 038 | 000 | 004 | |
| 25PT800B/19 | FL1.17AA | 7136 | FQ916MF/LIF | 020 | 064 | 000 | 000 | 000 |
| 25PT802B/19 | FL1.17AA | 7136 | FQ916MF/L MK2 | 084 | 064 | 000 | 000 | 016 |
| 25PT900A/19 | FL2.16AA | 7142 | FQ916MF/LIF | 020 | 068 | 000 | 004 | 001 |
| 25PT902B/19 | FL2.26AA | 7142 | FQ916MF/L MK2 | 018 | 068 | 000 | 004 | 001 |
| 25PT910A/19 | FL2.16 | 7141 | FQ916MF/LIF | 028 | 068 | 000 | 006 | |
| 28PT800A/19 | FL1.17 | 7136 | FQ916MF/LIF | 020 | 064 | 000 | 000 | |
| 28PT800B/19 | FL1. 1 7AA | 7136 | FQ916MF/LIF | 020 | 064 | 000 | 000 | 000 |
| 28PT802B/19 | FL1.17AA | 7136 | FQ916MF/L MK2 | 084 | 064 | 000 | 000 | 016 |
| 28PT840A/39 | FL1.17AA | 7136 | FQ916MF/LIF | 020 | 064 | 000 | 032 | 000 |
| 28PT842B/19 | FL1.17AA | 7136 | FQ916MF/L MK2 | 084 | 064 | 000 | 000 | 016 |
| 28PT842B/19 | FL1.16AA | 7142 | FQ916MF/L MK2 | 084 | 064 | 000 | 000 | 016 |
| 28PT900A/19 | FL2.16 | 7142 | FQ916MF/LIF | 028 | 068 | 000 | 004 | |
| 28PT910A/19 | FL2.16 | 7141 | FQ916MF/LIF | 028 | 068 | 000 | 006 | |
| 28PW960B/19 | FL2.24AA | 7111 | FQ916MF/LIF | 028 | 068 | 064 | 038 | 009 |
| 28PW962B/19 | FL2.24AA | 7111 | FQ916MF/L MK2 | 092 | 068 | 064 | 038 | 025 |
| 29PT820B/19 | FL4.27AA | 7136 | FQ916MF/LIF | 020 | 064 | 000 | 004 | 008 |
| 29PT822B/19 | FL4.27AA | 7136 | FQ916MF/L MK2 | 084 | 064 | 000 | 004 | 024 |
| 29PT900B/19 | FL2.26AA | 7142 | FQ916MF/LIF | 020 | 068 | 000 | 004 | 009 |
| 29PT902B/19 | FL2.26AA | 7142 | FQ916MF/L MK2 | 084 | 068 | 000 | 004 | 001 |
| 29PT910A/19 | FL2.16 | 7141 | FQ916MF/LIF | 028 | 068 | 000 | 006 | |
| 29PT910B/19 | FL2.26AA | 7141 | FQ916MF/LIF | 028 | 068 | 000 | 038 | 009 |
| 29PT912B/19 | FL2.26AA | 7141 | FQ916MF/L MK2 | 092 | 068 | 000 | 038 | 009 |
| 32PW960B/19 | FL2.24AA | 7111 | FQ916DMF/IF | 156 | 068 | 064 | 174 | 009 |
| 32PW962B/19 | FL2.24AA | 7111 | FQ916DMF/L MK2 | 220 | 068 | 064 | 174 | 025 |
| 32PW977A/19 | FL2.24AA | 7111 | FQ916DMF MH2 | 154 | 196 | 064 | 174 | 025 |
| 33PT700A/19 | FL1.1 | 7138 | FQ916MF/LIF | 020 | 000 | 000 | 000 | |
| 33PT700B/19 | FL1.10AA | 7138 | FQ916MF/LIF | 020 | 000 | 000 | 000 | 000 |
| 33PT702B/19 | FL1.10AA | 7138 | FQ916MF/L MK2 | 084 | 000 | 000 | 000 | 016 |
| 33PT702C/19 | FL1.20AA | 7138 | FQ916MF/L MK2 | 084 | 000 | 000 | 000 | 017 |
| 33PT910B/19 | FL2.26AA | 7141 | FQ916DMF/L MK2 | 156 | 068 | 000 | 038 | 009 |
| 33PT912B/19 | FL2.26AA | 7141 | FQ916DMF/L MK2 | 220 | 068 | 000 | 038 | 025 |
| 46PP960A/19 | FL1 PTV | 7141 | FQ916DMF/L MK2 | 156 | 079 | 064 | 000 | 000 |
| 46PP962A/19 | FL1 PTV AB | 7141 | FQ916DMF/L MK2 | 220 | 111 | 064 | 000 | 000 |
| 70TA8310/38 | FL1.1 7AA | 7136 | FQ916MF/LIF | 020 | 064 | 000 | 000 | |
| 70TA8330/38 | FL1.17AA | 7136 | FQ916MF/LIF | 084 | 064 | 000 | 000 | 016 |
| 70TA8331/18 | FL1.16A | 7142 | FQ916MF/L MK2 | 084 | 068 | 000 | 000 | 016 |
| 72TA7911/18 | FL1.17AA | 7136 | FQ916MF/LIF | 020 | 064 | 000 | 004 | 000 |
| 72TA7931/18 | FL4.17AA | 7136 | FQ916MF/L MK2 | 084 | 064 | 000 | 000 | 016 |
| 72TA7932/18 | FL4.16AA | 7142 | FQ916MF/L MK2 | 084 | 068 | 000 | 004 | 016 |
| 72TB7891/19 | FL4.17AA | 7136 | FQ916MF/LIF | 020 | 064 | 000 | 004 | 000 |
| 72TB7911/19 | FL4.17AA | 7136 | FQ916MF/L | 084 | 064 | 000 | 000 | 016 |
| 72TB7912/19 | FL4.16AA | 7142 | FQ916MF/L/MK2 | 084 | 068 | 000 | 004 | 016 |
| 25PV7506/39 | FL1.10 | 7137 | FQ916MF/IF | 028 | 000 | 000 | 000 | |

(suite du tableau page suivante)

| Référence | Châssis | RC | Tuner | OPTION | | | | |
|--------------|---------|------|------------|--------|-----|-----|-----|---|
| | | | | 1 | 2 | 2 | 4 | 5 |
| 25SL5501/39 | FL1.10 | 7138 | FQ916MF/IF | 020 | 000 | 000 | 000 | |
| 28PV7806/39 | FL1.10 | 7133 | FQ916MF/IF | 028 | 000 | 000 | 000 | |
| 28SL5501/39 | FL1.10 | 7138 | FQ916MF/IF | 020 | 000 | 000 | 000 | |
| 28SL5801/39 | FL1.10 | 7134 | FQ916MF/IF | 020 | 000 | 000 | 000 | |
| 28CL6976/39 | FL1.10 | 7137 | FQ916MF/IF | 028 | 000 | 000 | 000 | |
| 33ML8905/39 | FL1.16 | 7141 | FQ916MF/IF | 156 | 068 | 000 | 002 | |
| 21PT700A/19 | FL1.0 | 7114 | FQ816MF/IF | 020 | 003 | | | |
| 21SL5101/19 | FL1.0 | 7114 | FQ816MF/IF | 020 | 003 | | | |
| 21SL5756/19 | FL1.0 | 6114 | FQ816MF/IF | 004 | | | | |
| 25PV7966/39 | FL1.0 | 6403 | FQ816MF/IF | 028 | 001 | | | |
| 28PV7506/19 | FL1.0 | 7113 | FQ816MF/IF | 028 | 003 | | | |
| 28PV7976/39 | FL1.0 | 6403 | FQ816MF/IF | 028 | 001 | | | |
| 25SL5501/19B | FL1.0 | 7114 | FQ816MF/IF | 020 | 003 | | | |
| 25SL5776/39B | FL1.0 | 6414 | FQ816MF/IF | 004 | | | | |
| 25SL5776/39S | FL1.0 | 6414 | FQ816MF/IF | 020 | 001 | | | |
| 28SL5776/39B | FL1.0 | 6414 | FQ816MF/IF | 004 | | | | |
| 28SL5776/39S | FL1.0 | 6414 | FQ816MF/IF | 020 | 001 | | | |
| 28SL5801/19B | FL1.0 | 7114 | FQ816MF/IF | 020 | 003 | | | |
| 28CL6976/19Z | FL1.0 | 7101 | FQ816MF/IF | 028 | 003 | | | |
| 33PV7996/19B | FL1.0 | 6413 | FQ816MF/IF | 012 | 000 | | | |
| 33SL5901/19B | FL1.0 | 7114 | FQ816MF/IF | 020 | 003 | | | |
| 256597WQ/19S | FL1.0 | 7113 | FQ816MF/IF | 028 | 003 | | | |
| 256597WQ/39M | FL1.0 | 6413 | FQ816MF/IF | 028 | 001 | | | |
| 256575KR/19M | FL1.0 | 6414 | FQ816MF/IF | 004 | | | | |
| 256575KR/39M | FL1.0 | 6414 | FQ816MF/IF | 004 | | | | |
| 256575KR/19S | FL1.0 | 7114 | FQ816MF/IF | 020 | 003 | | | |
| 287597WQ/19M | FL1.0 | 6403 | FQ816MF/IF | 028 | | | | |
| 287597WQ/19S | FL1.0 | 7113 | FQ816MF/IF | 028 | 003 | | | |
| 287575KR/19M | FL1.0 | 6414 | FQ816MF/IF | 004 | | | | |
| 287575KR/39M | FL1.0 | 6414 | FQ816MF/IF | 004 | | | | |
| 287575KR/19S | FL1.0 | 7114 | FQ816MF/IF | 020 | 003 | | | |
| 339975KR/19B | FL1.0 | 6414 | FQ816MF/IF | 004 | | | | |
| 339975KR/39S | FL1.0 | 7114 | FQ816MF/IF | 020 | 003 | | | |
| 85RK5987/38S | FL1.0 | 7114 | FQ816MF/IF | 020 | 003 | | | |
| 70RK5797/18Z | FL1.0 | 7114 | FQ816MF/IF | 020 | 003 | | | |
| 25ML8300/19B | FL1.7 | 7115 | FQ816MF/IF | 020 | 007 | | | |
| 25ML8305/19B | FL1.7 | 7115 | FQ816MF/IF | 028 | 007 | | | |
| 25ML8500/19B | FL1.6 | 7111 | FQ816MF/IF | 020 | 071 | | | |
| 25ML8505/19B | FL1.6 | 7111 | FQ816MF/IF | 028 | 071 | | | |
| 25ML8766/19B | FL1.1 | 6411 | FQ816MF/IF | 004 | 004 | | | |
| 25ML8966/19B | FL1.1 | 6411 | FQ816MF/IF | 012 | 004 | | | |
| 28ML8600/19B | FL1.7 | 7115 | F0816MF/IF | 020 | 007 | | | |
| 28ML8605/19B | FL1.7 | 7115 | FQ816MF/IF | 028 | 007 | | | |
| 28ML8766/19B | FL1.1 | 6411 | FQ816MF/IF | 004 | 004 | | | |
| 28ML8776/19B | FL1.1 | 6411 | FQ816MF/IF | 004 | 004 | | | |

(suite du tableau page suivante)

| Référence | Chassis | RC | Tuner | OPTION | | | | |
|--------------|---------|------|-------------|--------|-----|-----|-----|---|
| | | | | 1 | 2 | 2 | 4 | 5 |
| 28ML8976/19B | FL1.1 | 6411 | FQ816MF/IF | 012 | 004 | | | |
| 28ML8800/19B | FL1.6 | 7111 | FQ816MF/IF | 028 | 071 | | | |
| 28ML8805/19B | FL1.6 | 7111 | FQ816MF/IF | 058 | 071 | | | |
| 33ML8905/19B | FL1.6 | 7111 | FQ816MF/IF | 156 | 071 | | | |
| 33ML8996/19B | FL1.1 | 6411 | FQ816MF/IF | 156 | 004 | | | |
| 28ML8762/19B | FL1.2 | 7117 | FQ816MF/IF | 020 | 071 | 064 | 000 | |
| 28ML8785/19B | FL1.2 | 7117 | FQ816MF/IF | 028 | 069 | 094 | 000 | |
| 28ML8916/19B | FL1.2 | 6411 | FQ816MF/IF | 020 | 004 | | | |
| 36ML8906/19B | FL1.2 | 6411 | FQ816MF/IF | 156 | 071 | | | |
| 36ML8965/39B | FL1.2 | 7117 | FQ816MF/IF | 156 | 069 | 192 | | |
| 70RK5816/18R | FL1.2 | 7112 | FQ816MF/IF | 020 | 071 | 064 | 000 | |
| 46ML0985/19B | FL1 PTV | 7117 | FQ816MF/IF | 156 | 079 | 094 | 000 | |
| 41ML0955/19B | FL1 PTV | 7117 | FQ816MF/IF | 156 | 079 | 064 | 000 | |
| 46PP960A/19 | FL1 PTV | 7111 | FQ916DMF/IF | 156 | 079 | 000 | 000 | |
| 46PP962A/19 | FL1 PTV | 7111 | FQ916DMF/IF | 220 | 111 | 000 | 000 | |

(Mise à jour le 25/01/01)